

# SP20

---

MANUAL MACHINES FOR LOOSE COMPONENTS DESIGNED TO CUSTOMER'S SPECIAL NEEDS

EXAMPLES OF FORMS:



---

SP20.05

---



---

SP20.07

---



---

SP20.08

---

PRODUCTION: 600 TO 1.000 P/H

---



SP20 line Pneumatic machines are manually operated equipment, individual component feed suitable to cut and form radial loose components. Machine's die assembly is designed to quickly reach the forms requested by the customer. It simplifies and speed up the time needed, reducing the number of steps in one single operation