

LOOSE COMPONENTS PREFORMING MACHINES



SP36.03 axial loose components forming





SP36.05 SPECIAL COMPONENTS CUTTING AND FORMING

PRODUCTION: 700 P/H

SP36 line pneumatic machines are manually fed equipment for individual loose components cutting and forming.

Machine's die assembly is designed to quickly reach the forms requested by the customer. It simplifies and speed up the time needed, reducing the number of steps to one single operation.