

Spares catalogue

Straightening and cutting machine

A075 S

Contents

01. Parts list A075 S	Page 2 – 6
02. Assembly drawings	
Enclosure and protective hood	A075 P 01.00
Drive.....	A075 P 02.00
Cutting tool.....	A075 P 03.00
Stick retainer	A075 P 04.00
Measurement value recorderA075 S 05.00

Straightening and cutting machine AO75 S - Spares catalogue

01. Parts list AO75 S

Item	Pcs	Drawing no.	Designation	Remarks
1	1	AO75 S T. 1	Base plate	
2	1	AO75 S T. 2	Side section, left	
2a	1	AO75 S T. 2a	Side section, right	
3	1	AO75 S T. 3	Cover plate	
4	2	AO75 S T. 4	Bracket	
5	1	AO75 S T. 5	Board	
6	1	AO75 S T. 6	Press on part	
7	2	AO75 S T. 7	Setting carrier	
8	2	AO75 S T. 8	Carrier	
10	4	AO75 S T. 10	Guide bar, 2x left, 2x right	*)
11	2	AO75 S T. 11	Straightening bearing	
12	2	AO75 S T. 12	Blade guide	
13	2	AO75 S T. 13	Clipping punch	*)
14	2	AO75 S T. 14	Cutting blade	*)
15	2	AO75 S T. 15	Bar	
16	4	AO75 S T. 16	Guide bar	
17	2	AO75 S T. 17	Retainer	
18	1	AO75 S T. 18	Adjustment bar	
19	2	AO75 S T. 19	Retainer	
20	1	AO75 S T. 20	Retainer	
27	2	AO75 S T. 27	Bearing plate	
28	4	AO75 S T. 28	Guide	
29	2	AO75 S T. 29	Cover plate	
30	2	AO75 S T. 30	Guide shoe	
31	1	AO75 S T. 31	Retainer	
32	1	AO75 S T. 32	Bottom guide part	

Straightening and cutting machine AO75 S - Spares catalogue

Item	Pcs	Drawing no.	Designation	Remarks
33	1	AO75 S T. 33	Measurement board	
34	2	AO75 S T. 34	Adjusting bearing	
35	1	AO75 S T. 35	Bearing strip	
36	1	AO75 S T. 36	Retaining plate	
38	1	AO75 S T. 38	Guide bearing	
39	1	AO75 S T. 39	Press-on part	
40	2	AO75 S T. 40	Retainer	
41	2	AO75 S T. 41	Connection strip	
44	4	AO75 S T. 44	Lining	
45	2	AO75 S T. 45	Drive strip	
46	1	AO75 S T. 46	Shifting square	
49	1	AO75 S T. 49	Bush	
50	1	AO75 S T. 50	Threaded spindle	*)
51	1	AO75 S T. 51	Insert	
52	1	AO75 S T. 52	Insert	
53	2	AO75 S T. 53	Bush	
54	1	AO75 S T. 54	Handle	
55	2	AO75 S T. 55	Eccentric bolt	*)
56	2	AO75 S T. 56	Adjusting spindle	
57	2	AO75 S T. 57	Counter nut	
58	5	AO75 S T. 58	Spring bolt	
59	1	AO75 S T. 59	Tracer pin	
60	1	AO75 S T. 60	Retaining bolt	
61	1	AO75 S T. 61	Retaining bolt	
62	2	AO75 S T. 62	Driving cam	*)
63	1	AO75 S T. 63	Threaded bolt	*)
64	2	AO75 S T. 64	Bearing bush	
65	1	AO75 S T. 65	Insert	

Straightening and cutting machine AO75 S - Spares catalogue

Item	Pcs	Drawing no.	Designation	Remarks
66	1	AO75 S T. 66	Conical spring washer	
67	1	AO75 S T. 67	Pin	
68	1	AO75 S T. 68	Maltese cross	*)
69	1	AO75 S T. 69	Driver disk	*)
70	2	AO75 S T. 70	Coupling	
71	1	AO75 S T. 71	Pin	
72	1	AO75 S T. 72	Toothed belt wheel	*)
73	1	AO75 S T. 73	Toothed belt wheel	*)
74	1	AO75 S T. 74	Curve	
75	1	AO75 S T. 75	Disk	
76	1	AO75 S T. 76	Disk	
77	4	AO75 S T. 77	Shaft	
78	2	AO75 S T. 78	Spindle	
79	2	AO75 S T. 79	Pin	
80	2	AO75 S T. 80	Guide bush	
81	2	AO75 S T. 81	Button	
82	8	AO75 S T. 82	Guide bush	
83	4	AO75 S T. 83	Insert	
84	2	AO75 S T. 84	Handle	
87	1	AO75 S T. 87	Bush	
88	1	AO75 S T. 88	Adjusting pin	
89	1	AO75 S T. 89	Adjusting bush	
90	1	AO75 S T. 90	Plate	
91	1	AO75 S T. 91	Retainer	
92	1	AO75 S T. 92	Belt	*)
93	1	AO75 S T. 93	Enclosure	
94	1	AO75 S T. 94	Storage for sticks	
95	1	AO75 S T. 95	Spring bolt	

Straightening and cutting machine AO75 S - Spares catalogue


Item	Pcs	Drawing no.	Designation	Remarks
96	1	AO75 S T. 96	Storage for sticks	
97	1	AO75 S T. 97	Storage for sticks	
98	2	AO75 S T. 98	Retainer for hood	
99	2	AO75 S T. 99	Bracket	
100	1	AO75 S T. 100	Front plate	
101	1	AO75 S T. 101	Sliding plate	
102	1	AO75 S T. 102	Front plate	
107	1	AO75 S T. 107	Front plate	
108	1	AO75 S T. 108	Back wall	
109	1	AO75 S T. 109	Bowl	
110	1	AO75 S T. 110	Hood	
111	1	AO75 S T. 111	Shifting square	
112	1	AO75 S T. 112	Chassis	
120	1		Shaft, hardened $\varnothing 10 \times 105$	
121	1		Shaft, hardened $\varnothing 10 \times 70$	
122	4		Shaft, hardened $\varnothing 10 \times 50$	
123	2		Shaft, hardened $\varnothing 10 \times 370$	
124	4		Deep groove ball bearing 608-zz	
125	2		Deep groove ball bearing 605-zz	
126	12		Recirculating ball bush N- 10V	
127	1		Needle bearing NK-8 /12	
128	4		Ball retainer $\varnothing 10 \times \varnothing 14 \times 38$	
129	4		Steel bush $\varnothing 14 \times \varnothing 20 \times 33$	
130	1		Shaft coupling, compl.	
131	1		Microswitch	

Straightening and cutting machine AO75 S - Spares catalogue


Item	Pcs	Drawing no.	Designation	Remarks
132	8		Spring pressure piece	
133	2		Swivelling drive DSR-16-180 P	
134			Set collar Ø10	
135	1		Tension spring	
136	2		Pressure spring D-42/4/4	
137	1		Safety switch AZ 15 zvr	
138	1		Safety switch clamp	
139	2		Front handle naturally anodised 10501-003	
140	2		Bow-type handle GN 425 – 235	with disk
141	3		Measurement transducer RECTI H20 – 10	
142	2		Spacer	

*) = recommended spares

Straightening nad cutting machine AO75 S - Spares catalogue



Straightening nad cutting machine AO75 S - Spares catalogue



Straightening nad cutting machine AO75 S - Spares catalogue

